

附表 7. 最嚴格試驗抽樣表

批 量	一 般 試 驗					分 項 試 驗								
	樣 品 數	嚴重缺點		一般缺點		輕微缺點		樣 品 數	嚴重缺點		一般缺點		輕微缺點	
		Ac	Re	Ac	Re	Ac	Re		Ac	Re	Ac	Re	Ac	Re
1~ 8	2	↓		↓		↓			↓		↓		↓	
9~ 15	2								↓		↓		↓	
16~ 25	3					0	1	2	0	1	0	1	0	1
26~ 50	5					↓			↓		↓		↓	
51~ 90	5								↓		↓		↓	
91~ 150	8			0	1			3	0	1	0	1	1	2
151~ 280	13			↓		1	2		↑		↑		↑	
281~ 500	20					2	3	5	0	1	0	1	1	2
501~ 1,200	32			1	2	3	4		↑		↑		↑	
1,201~ 3,200	50	0	1	2	3	5	6		↑		↑		↑	
3,201~ 10,000	80	↓		3	4	8	9	8	0	1	1	2	2	3
10,001~ 35,000	125	1	2	5	6	12	13		↑		↑		↑	