

附表 5. 寬鬆試驗抽樣表

批 量	一 般 試 驗						分 項 試 驗													
	樣 品 數	嚴重缺點		一般缺點		輕微缺點		樣 品 數	嚴重缺點		一般缺點		輕微缺點							
		Ac	Re	Ac	Re	Ac	Re		Ac	Re	Ac	Re	Ac	Re						
1~ 8	2	↓		↓	↓			↓		↓		↓								
9~ 15	2			↓																
16~ 25	2			0 2																
26~ 50	2			↑										↓						
51~ 90	2			↓	1 2									1 2						
91~ 150	3				1 3									1 3						
151~ 280	5				1 2									2 4						
281~ 500	8	0 1	1 3	2 5	1	0 1	0 1	0 2	↑		↑		↑							
501~ 1,200	13	↓		2 4	3 6	↑		↑												
1,201~ 3,200	20			2 5	5 8															
3,201~ 10,000	32			1 2	3 6	7 10														
10,001~ 35,000	50	1 3	5 8	10 13	2	0 1	0 1	1 2												