

附表 6. 嚴格試驗抽樣表

批 量	一 般 試 驗						分 項 試 驗							
	樣 品 數	嚴重缺點		一般缺點		輕微缺點		樣 品 數	嚴重缺點		一般缺點		輕微缺點	
		Ac	Re	Ac	Re	Ac	Re		Ac	Re	Ac	Re	Ac	Re
1~ 8	2	↓		↓		↓		1	↓	↓	↓			
9~ 15	2													
16~ 25	3													
26~ 50	5			↓	↓	↓	↓	↓	↓	↓	↓			
51~ 90	5													
91~ 150	8													
151~ 280	13			↓	↓	1 2	2 3	2	↑	↑	↑			
281~ 500	20													
501~ 1,200	32													
1,201~ 3,200	50	↓		3 4	8 9		↑	↑	↑					
3,201~ 10,000	80			5 6	12 13									
10,001~ 35,000	125	1 2	8 9	18 19	5	0 1	0 1	1 2						